

iQ-Series Firmware Update

Version 2.2 - (22 January 2019)

Turbosound iQ-Series

Firmware update for Turbosound iQ-Series amplified speakers.

We recommend downloading and installing the most recent firmware from turbosound.com to ensure optimal performance of your product.

Your speaker models can either contain Version 1 or Version 2 firmware, which was introduced as a running change in 2018. There is no functionality or performance differences in hardware A and B and this change was due to silicon obsolescence only. Please note this does mean the software in the display/menu will show as FW: V2.2. Both Models HW:A & HW:B are fully supported from a warranty perspective.

To install the firmware update on Turbosound DSP modules:

1. press SETUP while switching the unit on
2. Connect your Windows PC to the speaker's USB port
3. Then run the executable "TURBOSOUND UsbUpdate_V2.2.exe" that you downloaded and unpacked from our website.

2.2 (2019-01-22)

New features:

- Improved input modes: Analog, Ultranet and Auto.
- Separate P16 page for Ultranet setup.
- Active Ultranet channel is shown on main screen.
- Improved parameter save and several fixes.
- Improved limiter behavior.

1.9 (2016-07-01)

New features:

- Improved ULTRANET stability
- Improved behaviour in low temperature operation (below 0 °C)
- Support for upcoming TS products (new series)

1.7 (2014-06-10)

New features:

- support for NuQ, TCS and TSP series
- support for Turbosound Edit remote application

1.0 (2014-12-04)

- iQ series production release